

**MODERNIZATION  
PROGRAM  
LIAISON OFFICE**

**DEFINITIONS:**

**(Dust)** - This activity could possibly generate dust.

**(IAQ)** - This activity could possibly be a source of Indoor Air Quality concerns.

**(Noise)** - This activity could generate noise.

**(ACM)** - Asbestos containing material.

If any of the above conditions becomes an irritant, please call 208.7560 immediately.

**What is SMACNA?**

SMACNA is an acronym for the Sheet Metal and Air Conditioning Contractor's National Association. NIOSH has requested that construction complies with these guidelines. It is important to note that no industry standard exists for the percentile of compliance. GSA conducts a daily checks of the construction area to ensure the contractor is in compliance with these guidelines.

**GSA CONTRACTOR'S  
COMPLIANCE WITH  
SMACNA GUIDELINES.**

**RESULTS  
FOR THE  
PERIOD**

**06-29-09 to 07-03-09**

**99%  
Green**

# Behind the Barricade

## Plan of the Week

JULY 06-JULY 12, 2009

### Modernization Activities Wing 3

**Wing 3**

**7th Floor**

**East/West**

- Paint
- Hang drywall close in at stair 30
- Finish drywall at stair 30
- Plaster Patching
- Prime paint
- Caulk windows

**6th Floor**

**East/West**

- Tape & Finish sand sheet rock
- Install trims
- Prime paint & paint
- Caulk windows
- Prime paint
- Point up

**Mechanical- Floor**

**East/West**

- Connect equipment
- Set door frames
- Install light fixtures
- Install air handling unit pumps

**5th Floor**

**East/West**

- Rough in toilet exhaust
- Insulate plumbing pipe
- Pour chase infill
- Fire stop exterior wall at chase
- Caulk windows

**4th Floor**

**East/West**

- Rough in plumbing risers
- Install control wires
- Test plumbing risers

- Insulate plumbing pipe
- Fire stop exterior wall at chase
- Caulk windows

**3rd Floor**

**East/West**

- Connect fan coil units
- Install control wires
- Framing at stair 30
- Set door frames
- Caulk windows

**2nd Floor**

**East/West**

- Connect fan coils
- Test sprinkler pipe
- Test fire alarm wire
- Plaster patching
- Texture ceilings

**1st Floor**

**East/West**

- Plaster patching
- Connect fan coil units
- Rough in mechanical pipe
- Insulate walls
- Rough in conduit
- Lead abatement

**Elevator 11/12/13/14**

- Modify equipment and hoistways
- Concrete pads
- Install relief air

