

**MODERNIZATION
PROGRAM
LIAISON OFFICE**

DEFINITIONS:

(Dust) - This activity could possibly generate dust.

(IAQ) - This activity could possibly be a source of Indoor Air Quality concerns.

(Noise) - This activity could generate noise.

(ACM) - Asbestos containing material.

If any of the above conditions becomes an irritant, please call 208.7560 immediately.

What is SMACNA?

SMACNA is an acronym for the Sheet Metal and Air Conditioning Contractor's National Association. NIOSH has requested that construction complies with these guidelines. It is important to note that no industry standard exists for the percentile of compliance. GSA conducts a daily checks of the construction area to ensure the contractor is in compliance with these guidelines.

**GSA CONTRACTOR'S
COMPLIANCE WITH
SMACNA GUIDELINES.**

**RESULTS
FOR THE
PERIOD
07-06-09 to 07-10-09**

**99%
Green**

Behind the Barricade

Plan of the Week

JULY 13-JULY 19, 2009

Modernization Activities Wing 3

Wing 3

7th Floor

East/West

- Install Trim & Crown
- Install surface non metallic raceway
- Install cable tray
- Prime paint

6th Floor

East/West

- Install trim & crown
- Install surface non metallic raceway
- Install cable tray

Mechanical- Floor

East/West

- Connect duct to equipment
- Install air handling pumps
- Connect pipe to equipment
- Insulate heating ventilation & air condition
- Set door frames

5th Floor

East/West

- Insulate plumbing pipe
- Prime paint
- Install trim & crown
- Plaster patching
- Reinstall stone base

4th Floor

East/West

- Toilet room infill's
- Prime paint
- Install trim & crown
- Inspect walls
- Masonry patching
- Plaster patching

3rd Floor

East/West

- Insulate plumbing pipe
- Toilet room infill's steel
- Toilet room concrete
- Concrete infill's
- Set door frames

2nd Floor

East/West

- Megger fire alarm wire
- Insulate mechanical pipe
- Insulate plumbing pipe
- Set door frames
- Frame walls and chases
- Rough in toilet exhaust

1st Floor

East/West

- Plaster patching ceilings
- Hydro sprinkler system
- Insulate heating ventilation & air condition duct
- Rough in sprinkler pipe
- Rough in heating ventilation & air condition
- Rough in plumbing

Elevator 11/12/13/14

- Modify equipment and hoistways
- Concrete modifications
- Install relief air

