

OAS-25A
(4/18)



Interagency Aviation SAFETY ALERT



No. IA SA 26-01

Date: January 28, 2026

Page 1 of 2

Subject: Recall of Orion Skyblazer II Red XLT Aerial Signal

Area of Concern: Flight Safety

Distribution: All Aviation Operations

Discussion: This Safety Alert is issued to communicate an urgent recall and Product Quarantine Notice from Orion Safety Products for Skyblazer II Red XLT Aerial Signals following reports of unsafe performance and malfunction, including improper ignition and failure to function as intended.

Orion's recall guidance requires immediate action:

- Stop using affected products immediately.
- Quarantine all identified items until further notice.

Review Orion's recall guidance at <https://www.orionsignals.com/wp-content/uploads/2026/01/Updated-Skyblazer-Recall-Notice-12.26-Final179634068.2-C.pdf>

Although these signal flares are commonly associated with maritime use, they are also carried aboard aircraft as part of aviation survival kits and emergency signaling equipment, presenting a direct aviation safety concern. Additionally, the FAA has published a [Special Airworthiness Information Bulletin \(SAIB\)](#) regarding this issue.

- **Affected Products:** The following Skyblazer II Red XLT Aerial Signals are subject to urgent recall and quarantine (see images on page 2): Product Number 769, 855, and 859 with expiration dates of August 2028 through April 2029
- Product Number 855A with manufacture dates of March 2025 through November 2025

Any Skyblazer II Red XLT aerial signal meeting any of the above criteria must be considered recalled and quarantined immediately. Additional information is available on [Orion Safety Products' official website](#).



Item No. 769



Item No. 855/855A (sold individually)



Item No. 859

/s/ Keith C. Raley

Keith C. Raley
Chief, Aviation Safety, Training, Program
Evaluation, and Quality Management
DOI, Office of Aviation Services

/s/ Lori Clark

Lori Clark
Branch Chief - Aviation Safety Management
Systems
USDA, Forest Service