



United States Department of the Interior
Office of Aviation Services
300 E. Mallard Dr., Ste 200
Boise, Idaho 83706-3991

DOI OPERATIONAL PROCEDURES MEMORANDUM (OPM) - 46

Subject: Accepted Procedures for the Mixing and Loading of Retardant into SEAT Aircraft

Effective Date: January 1, 2016

Supersedes: OPM-46 dated January 1, 2015

Distribution: A, B, & C

Expiration: December 31, 2016

1. Purpose. This OPM establishes policy for the mixing and loading of retardant into Single Engine Air Tanker (SEAT) aircraft.

2. General. There have been several recent aircraft incidents that involved the overloading of SEAT aircraft with liquid concentrate (LC) retardant as a result of mixing or loading procedures. These procedures included loading LC directly into aircraft from bulk storage tanks while utilizing various types of hardware devices that were intended to blend retardant being pumped directly from the bulk tanks to the aircraft. These hardware devices have included Canadian Y Blenders, "SEAT" Y Blenders, pre-calibration tanks and other locally fabricated hardware. However, serious overloading can occur when pure LC is loaded into an aircraft without being mixed with the appropriate ratio of water.

3. Policy. In an effort to eliminate the possibility of overloading an aircraft with an incorrect mix of retardant, the following procedures apply immediately:

Both powdered and liquid bulk materials will be blended in a mixing container prior to being introduced into the aircraft. In order to maintain quality control and safe flight operations, no bulk material will be loaded into an aircraft prior to being mixed to the proper ratio and checked by refractometer or other accepted method. The practice of loading an aircraft with bulk material and then adding water is not an acceptable method of mixing retardant.

All personnel engaged in the loading of retardant aboard SEAT aircraft must be knowledgeable of, and fully trained on, the use of retardant loading systems for SEAT aircraft.

Additionally, this policy has been coordinated with all DOI bureaus that utilize SEAT aircraft and with the USDA/Forest Service.

Director, Office of Aviation Services